

# Internal Flare Update for Bumper Mount Speaker



PRODUCT UPDATE • MARKET ADVISORY

MA:0133 • 02/2025

We are announcing a change to the internal plastic flare in our bumper mount speaker models **SP123BCC** and **SP123BMC**.

## What's Changing?

- The internal plastic flare, previously Grey, will now be Black.
- This component is located behind the siren's flange and is not visible when installed.

The speaker's functionality, installation process, and external appearance have not been changed. If you have any questions about this change, please contact your Whelen sales representative.



SP123BCC and SP123BMC

**WARNING:** This product may contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. For more information, visit [whelen.com/regulatory](http://whelen.com/regulatory).